

Site Radon Inspection Report

Date: March 31, 2000

Claude States
118 State Rte. 228
Odessa, NY 14869

Test Location: 118 State Rte. 228
Odessa, NY 14869

Individual Canister Results: ____

Radon Level	: 0.1 pCi/L	Location	: CRWL SPC.
Canister ID #	: 1574170	Test Start	: 03/14/2000 @ 16:30
Canister Type	: PASS-DIF-3	Test Stop	: 03/19/2000 @ 08:30

The reported results indicate that radon levels in your home are below the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). Since radon levels can vary significantly from season to season it is advisable to conduct at least one short-term test during the winter heating season, if you have not done so already. The EPA recommends retesting if your living patterns change and you begin occupying a lower level of your home, such as a basement.

General radon information may be obtained by consulting the EPA booklet: A Citizen's Guide To Radon (EPA Document #402-K92-001, 2nd Ed., May 1992). To request a copy, please contact your state health department. New York State residents may contact the health department at 800-458-1158 ext.451.

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air.

Jason Z. Esposito
Laboratory Director

